

Michigan Barn and Farmstead Survey

Ed Jones

March 15, 2009

SURVEYOR

DATE

PROPERTY #

Miller

OWNER'S NAME

Whiteside

COUNTY

COMMON NAME

1385 Meridian Rd.

PROPERTY ADDRESS

same

OWNER'S ADDRESS

Walnut

TOWNSHIP

B

SECTION

42.493242

GPS COORDINATES

N 42° 29.5945'

LATITUDE

-83.552583

W 83° 33.155'

LONGITUDE

BARN

CONDITION

- good
- fair
- poor
- altered
- ruins

ROOF SHAPE

- gable
- gambrel
- gothic
- half monitor
- mansard
- monitor
- ogee
- round
- shed

ROOF COVERING

- asphalt shingle
- slate
- steel: corrugated
- steel: ribbed
- steel: standing seam
- wood shake
- wood shingle
- other:
- hay hood

SIDING

- steel: corrugated
- steel: ribbed
- wood: battens
- wood: horizontal
- wood: v-groove
- wood: vertical
- other:

PAINTING / DECORATION

- Painted?
- no
 - yes. Color: green
- Names/dates/decoration?
- no
 - yes. Describe: white trim
- name: "Miller 1905"

OTHER FEATURES

- cupola
- dormer
- lightning rod (2)
- ventilator (2)
- weather vane (1)
- other:

FOUNDATION

- bank
- bridged
- on grade
- piers
- raised
- ramped

FOUNDATION MATERIALS

- boulders
- cement block
- eld stone
- eld stone - split
- eld stone - dressed
- glazed tile
- poured concrete

FARMHOUSE

CONDITION

- good
- fair
- poor
- altered
- ruins

ROOF SHAPE

- gable
- gambrel
- gothic
- hip
- mansard
- shed
- other:
- gable @ rear

ROOF COVERING

- asphalt shingle
- slate
- steel: corrugated
- steel: ribbed
- steel: standing seam
- tile
- wood shake
- wood shingle
- other:

SIDING

- color: _____
- aluminum
 - brick
 - concrete block
 - stone
 - vinyl
 - wood: horizontal
 - wood: vertical
 - other:
- rear ell

OTHER FEATURES


- cupola
- dormer
- lightning rod
- porch
- weather vane
- other:

FOUNDATION MATERIALS

- cement block
- eld stone
- eld stone - split
- eld stone - dressed
- glazed tile
- poured concrete
- other:

facing north

SKETCH OF FARMSTEAD LAYOUT



FARMSTEAD BUILDINGS

If building does not exist, check the N/A box.

CONDITION	ROOF SHAPE	ROOF MATERIAL	SIDING MATERIAL	FOUNDATION TYPE	FOUNDATION MAT'L	OTHER FEATURES (color, trim, etc.)
CHICKEN COOP <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input type="checkbox"/> N/A	monitor	corrugated steel	horiz. wood	?	?	
CORNCRIB <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input type="checkbox"/> N/A	gable	asphalt shingle	horiz. wood	piers	concrete	side walls slant out at top
GRANARY <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input checked="" type="checkbox"/> N/A						
HOG HOUSE <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input checked="" type="checkbox"/> N/A						
MACHINE SHED <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input checked="" type="checkbox"/> N/A						
MILK HOUSE <input type="checkbox"/> good <input checked="" type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input type="checkbox"/> N/A	gable	asphalt shingle	concrete block	on grade →		
OUTHOUSE <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input checked="" type="checkbox"/> N/A						
SILO <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input type="checkbox"/> N/A	gambrel	wood shingles	glazed tile			
WINDMILL <input checked="" type="checkbox"/> tower <input checked="" type="checkbox"/> wheel <input checked="" type="checkbox"/> gearbox <input checked="" type="checkbox"/> tail <input type="checkbox"/> N/A	rusty, but still turning & complete					
OTHER: modern garage <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input type="checkbox"/> N/A	gable	asphalt shingle	vinyl	on grade	concrete block	
OTHER: _____ <input type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> poor <input type="checkbox"/> altered <input type="checkbox"/> ruins <input checked="" type="checkbox"/> N/A						